Rotorcraft Directorate ASW-100 presents:

2016 International Rotorcraft Safety Conference

Part 27 Helicopters presentation provides an overview of the Rotorcraft Directorate's Safety Continuum policy for all CAR 6/Part 27 certificated rotorcraft (normal-category helicopters). The presentation describes the rational and benefits of developing separate "classes" for normal-category rotorcraft, and how those classes are applied to create a tiered approach to the SAE APR-4754A certification standards for systems and equipment.

Event Details

Tue, Oct 25, 2016 - 13:15 CDT Hurst Conference Center 1601 Campus Drive

Hurst, TX 76054



Contact: Eugene Trainor 817-222-5123 eugene.trainor@faa.gov

Select #: SW1371681 FPM Daniel Vengen **Directions:** Driving from Dallas From TX-183/TX-121 West
• Exit Precinct Line Road
• Continue through the light

Continue through the light
 Turn right on Campus Drive

• Furn right on Campus Drive Driving from Fort Worth

From TX-183/TX-121 East

Exit Precinct Line Road

• Turn left on Precinct Line Road

 Turn left on Thousand Oaks Drive Driving from DFW International

Driving from DFW International South Entrance

• Take TX-183 West for approximately 8 miles

Exit Precinct Line Road

• Continue through the light

 Turn right on Campus Drive Driving from DFW International

North Entrance

• Take TX-114 West/TX121 South for approximately 3 miles

 Merge onto TX-121 South towards Fort Worth for approximately 10 miles

Exit Precinct Line Road

• Continue through the light

• Turn right on Campus Drive

A message from the National FAASTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area.

Sign up for the FAA's safety services at www.FAASafety.gov!

The FAA Safety Team (FAASTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.